DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/20/2007 FORM APPROVED OMB NO. 0938-0391

NAME OF PROVIDER OR SUPPLIER BROUGHTON HOSP SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL RAGY OR LSC IDENTIFYING INFORMATION) TAG	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION		PLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED	
MAKE OF PROVIDER OR SUPPLIER BROUGHTON HOSP SUMMARY STATEMENT OF DEFICIENCIES (AU ID PRETIX REGULATORY OR LSC IDENTIFYING INFORMATION) FREERIX REGULATORY OR LSC IDENTIFYING INFORMATION) K 025 NFPA 101 LIFE SAFETY CODE STANDARD Smoke barriers are constructed to provide at least a one half hour fire resistance rating in accordance with 8.3. Smoke barriers may terminate at an atrium wall. Windows are protected by fire-rated glazing or by wired glass panels and steel frames. A minimum of two separate compartments are provided on each floor. Dampers are not required in duct penetrations of smoke barriers in fully ducted heating, ventilating, and air conditioning systems. 19.3.7.3, 19.3.7.5, 19.1.6.3, 19.1.6.4 This STANDARD is not met as evidenced by: By observation there was a gap between the smoke doors near room 165. Identify doors throughout the building that may have a gap greater than 1/8 inch. K 130 OTHER LSC DEFICIENCY NOT ON 2786 This STANDARD is not met as evidenced by: By observation throughout the facility there were lights without lens covers and or the clear sleeve				A. BUILDING 03 - HOEY		03 - HOEY		
BROUGHTON HOSP 1000 S STERLING ST	344002			B. WING			11/16/2005	
PREFIX TAG (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) K 025 NFPA 101 LIFE SAFETY CODE STANDARD Smoke barriers are constructed to provide at least a one half hour fire resistance rating in accordance with 8.3. Smoke barriers may terminate at an atrium wall. Windows are protected by fire-rated glazing or by wired glass panels and steel frames. A minimum of two separate compartments are provided on each floor. Dampers are not required in duct penetrations of smoke barriers in fully ducted heating, ventilating, and air conditioning systems. 19.3.7.3, 19.3.7.5, 19.1.6.3, 19.1.6.4 This STANDARD is not met as evidenced by: By observation there was a gap between the smoke doors near room 165. Identify doors throughout the building that may have a gap greater than 1/8 inch. K 130 OTHER LSC DEFICIENCY NOT ON 2786 This STANDARD is not met as evidenced by: By observation throughout the facility there were lights without tens covers and or the clear sleeve					10	000 S STERLING ST		
Smoke barriers are constructed to provide at least a one half hour fire resistance rating in accordance with 8.3. Smoke barriers may terminate at an atrium wall. Windows are protected by fire-rated glazing or by wired glass panels and steel frames. A minimum of two separate compartments are provided on each floor. Dampers are not required in duct penetrations of smoke barriers in fully ducted heating, ventilating, and air conditioning systems. 19.3.7.3, 19.3.7.5, 19.1.6.3, 19.1.6.4 This STANDARD is not met as evidenced by: By observation there was a gap between the smoke doors near room 165. Identify doors throughout the building that may have a gap greater than 1/8 inch. K 130 OTHER LSC DEFICIENCY NOT ON 2786 This STANDARD is not met as evidenced by: By observation throughout the facility there were lights without lens covers and or the clear sleeve	PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		PREFIX (EACH CORRECTIVE ACTION TAG CROSS-REFERENCED TO THE A		(EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO	.D BE	(X5) COMPLETION DATE
By observation throughout the facility there were lights without lens covers and or the clear sleeve	K 025	Smoke barriers are constructed to provide at least a one half hour fire resistance rating in accordance with 8.3. Smoke barriers may terminate at an atrium wall. Windows are protected by fire-rated glazing or by wired glass panels and steel frames. A minimum of two separate compartments are provided on each floor. Dampers are not required in duct penetrations of smoke barriers in fully ducted heating, ventilating, and air conditioning systems. 19.3.7.3, 19.3.7.5, 19.1.6.3, 19.1.6.4 This STANDARD is not met as evidenced by: By observation there was a gap between the smoke doors near room 165. Identify doors throughout the building that may have a gap greater than 1/8 inch. NFPA 101 MISCELLANEOUS OTHER LSC DEFICIENCY NOT ON 2786		K 025				12/19/05
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X6) DATE		By observation throug lights without lens con for protection.	ghout the facility there were were were were were and or the clear sleeve					(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.